Mound 5 has PCBs but not RCRA metals. Shouldn't that be a separate waste stream?  We can discuss next week Thank you Chris  Begin forwarded message:  From: Nonresponsive based on revised scope (@erllc.com> Date: October 11, 2019 at 12:28:38 PM EDT To: "Wagner, Christine" "Wagner Christine@epa.gov> Subject: Fwd: Shiloh Church / 3-5467[3061459]  Hi. It looks like mound 5 (east/west) mound only has pub. Put that in the mound pile? Mound 3 confirmation samples look great. Enjoy the day  Sent from my Verizon, Samsung Galaxy smartphone	To: Nonresponsive based on revised scope @erllc.com]  From: Wagner, Christine[/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=12068C1889924ECF96F692831F0C77D4-CWAGNE02]  Sent: Fri 10/11/2019 9:35:45 PM (UTC)  Subject: Fwd: Shiloh Church / 3-5467[3061459]  3061459 935725 fr.PDF  ATT00001.htm
We can discuss next week Thank you Chris  Begin forwarded message:  From: Nonresponsive based on revised scope @erllc.com> Date: October 11, 2019 at 12:28:38 PM EDT To: "Wagner, Christine" <\widetilde{Wagner, Christine@epa.gov}\ Subject: Fwd: Shiloh Church / 3-5467[3061459]  Hi. It looks like mound 5 (east/west) mound only has pub. Put that in the mound pile? Mound 3 confirmation samples look great. Enjoy the day  Sent from my Verizon, Samsung Galaxy smartphone	Monresponsive based on revised scope
Thank you Chris  Begin forwarded message:  From: Nonresponsive based on revised scope @crilc.com> Date: October 11, 2019 at 12:28:38 PM EDT To: "Wagner, Christine" < Wagner Christine@epa.gov> Subject: Fwd: Shiloh Church / 3-5467[3061459]  Hi. It looks like mound 5 (east/west) mound only has pub. Put that in the mound pile? Mound 3 confirmation samples look great. Enjoy the day  Sent from my Verizon, Samsung Galaxy smartphone	Mound 5 has PCBs but not RCRA metals. Shouldn't that be a separate waste stream?
From: Nonresponsive based on revised scope	Thank you
To: "Wagner, Christine" < Wagner. Christine@epa.gov > Subject: Fwd: Shiloh Church / 3-5467[3061459]  Hi.  It looks like mound 5 (east/west) mound only has pub. Put that in the mound pile? Mound 3 confirmation samples look great.  Enjoy the day  Sent from my Verizon, Samsung Galaxy smartphone  Original message  From: Nonresponsive based on revised scope @Alsglobal.com Date: 10/10/19 16:37 (GMT-05:00)  To: Nonresponsive based on revised scope  @erllc.com > Subject: Shiloh Church / 3-5467[3061459]  The following reports are attached:	Begin forwarded message:
It looks like mound 5 (east/west) mound only has pub. Put that in the mound pile? Mound 3 confirmation samples look great.  Enjoy the day  Sent from my Verizon, Samsung Galaxy smartphone  Original message  From: Nonresponsive based on revised scope @Alsglobal.com  Date: 10/10/19 16:37 (GMT-05:00)  To: Nonresponsive based on revised scope @erllc.com> Subject: Shiloh Church / 3-5467[3061459]  The following reports are attached:	<b>To:</b> "Wagner, Christine" < <u>Wagner.Christine@epa.gov</u> >
Original message  From: Nonresponsive based on revised scope @Alsglobal.com  Date: 10/10/19 16:37 (GMT-05:00)  To: Nonresponsive based on revised scope @erllc.com> Subject: Shiloh Church / 3-5467[3061459]  The following reports are attached:	It looks like mound 5 (east/west) mound only has pub. Put that in the mound pile? Mound 3 confirmation samples look great.
Subject: Shiloh Church / 3-5467[3061459]  The following reports are attached:	Sent from my Verizon, Samsung Galaxy smartphone
	Subject: Shiloh Church / 3-5467[3061459]  The following reports are attached:
End Of List	End Of List

Confidentiality Warning: This e-mail and any attachments contain information intended only for the use of the individual or entity named above. If the reader of this e-mail is not the intended recipient or the employee or agent responsible for delivering it to the intended recipient, any dissemination, publication or copying of this e-mail is strictly prohibited. Although this email has been scanned for malware, the sender does not accept any responsibility for any loss, disruption or damage to your data or computer system that may occur while using data contained in, or transmitted with, this e-mail. If you have received this e-mail in error, please immediately notify by return e-mail. Thank you.

